

報道資料

日付	令和 7 年 2 月 5 日(水)
担当課	企業局下水道事業課
電話番号	0742-34-5276

奈良市公共下水道管路の緊急点検について

- ・ 1 月 28 日に埼玉県八潮市で下水道管路に起因した道路陥没事故が発生しました。
- ・ 国土交通省より下水道管理者に下水道管路の緊急点検の要請がありました。
- ・ 点検対象は、晴天時 1 日最大汚水量 300, 000m³ 以上で口径 2, 000mm 以上の下水道管路で、本市の施設はこの条件に該当する管路はありません。
- ・ 奈良市は 2, 000mm 以上の大きな口径の管路を保有していることから、市独自の取組として、緊急点検を行います。

(点検対象箇所)

名称	口径	延長	場所		経過年数
			下流端	上流端	
佐保分水幹線	φ 2600mm	L=1,709m	法華寺町2番の4地先から	法蓮町1218番地先まで	21年
大宮分水幹線	φ 2400mm	L=1,016m	三条添川町118番の3地先から	芝辻町二丁目144番の1地先	35年
高畑分水幹線	φ 2400mm	L=1,551m	西木辻町63番地の4から	東紀寺町一丁目700番地の1地先まで	32年

(点検方法)

潜行目視点検：マンホール内に調査員が入り、土砂の堆積状況や管路の状況などを目視で確認します。

(点検期間)

令和 7 年 2 月 1 2 日 (水) ～ 2 月 1 3 日 (木)

※なお、点検により施設に異状があった場合は、補修などの適切な措置を講じます。

The map illustrates the Tama River watershed, highlighting three main sub-watersheds: Saiho, Omiya, and Takahata. The Saiho Watershed (佐保分水幹線) is located in the upper left, the Omiya Watershed (大宮分水幹線) is in the center, and the Takahata Watershed (高畑分水幹線) is in the lower right. The map also shows the Daianji 1st and 2nd Treatment Areas (大安寺第1処理分区 and 大安寺第2処理分区). A scale bar at the bottom indicates distances up to 1.5 km.