

耐震化状況一覧表

H31.4.1現在

【小学校】

地区	番号	施設名	棟番号	枝番号.1	枝番号.2	枝番号.3	枝番号.4	建物区分	建築年	構造	階数	延べ面積	耐震性能等	耐震診断(2次診断)結果			補強後			2次診断年度	補強設計年度	備考			
														IS値	q値	CTuSD値	IS値	IS値	q値				CTuSD値		
1	1	椿井小学校	13					校舎	H16	R	3	2,030	新耐震												
	2		14					校舎	H16	R	3	1,822	新耐震												
	3		10	1	2			体育館	H4	R	4	995	新耐震												
2	4	飛鳥小学校	6					校舎	S42	R	3	1,753	耐震補強済	0.25		0.33		0.86		0.33	H8	H8			
	5		12					校舎	S46	R	2	632	耐震補強済	0.35	0.33		1.3	4.73			H11	H12			
	6		14	1				校舎	S49	R	3	1,881	耐震補強済	0.54	1.8		0.9	3.07			H8	H12			
	7		14	2	3			校舎	S52	R	3	566	耐震補強済	0.53		0.43	0.5	0.77		0.43	H24	H25			
	8		26					校舎	H21	S	1	285	新耐震												
	9		27					校舎	H27	R	2	1,007	新耐震												
	10		24					体育館	H6	R	1	881	新耐震												
3	11	鼓阪小学校	2					校舎	S38	R	3	1,393	耐震補強済	0.48	1.1		0.96	1.83			H8	H9			
	12		3				校舎	S40	R	3	1,373	耐震補強済	0.34		0.37	0.29	0.7		0.49	H24	H25				
	13		4				校舎	S42	R	3	1,665	耐震補強済	0.33		0.43	0.31	0.76		0.83	H24	H25				
	14		1	1	2			体育館	S11	R	1	1,155	耐震補強済	0.38		0.16		0.8		0.85	H21	H22			
4	15	済美小学校	6					校舎	S45	R	3	1,525	耐震補強済	0.43		0.48	0.34	0.8		0.89	H21	H23			
	16		13				校舎	S49	R	3	264	耐震補強済	0.47		0.4	0.56	0.89		0.41	H21	H23				
	17		14				校舎	S49	R	2	726	耐震性有	0.77		0.39	0.4					H21				
	18		25				校舎	H18	R	3	1,886	新耐震													
	19		26				校舎	H19	R	3	1,867	新耐震													
	20		23				体育館	H8	R	2	800	新耐震													
5	21	佐保小学校	1	1				校舎	S45	R	3	1,397	耐震性有	0.85		0.86						H9			
	22		2	1	2	3		校舎	S32	R	3	2,710	耐震補強済	0.44		0.48	0.39	0.71		0.57	H22	H23			
	23		3-6	3-1	3-2	3-3	6-0		校舎	S42	R	3	2,046	耐震補強済	0.37		0.49	0.27	0.73		0.78	H20	H22		
	24		3	5	6			校舎	S52	R	3	501	耐震補強済	0.62		0.34		0.78		0.32	H9	H11			
	25		21	1	2			校舎	S54	R	2	260	耐震性有				1.24								
	26		15					体育館	S47	R	2	815	耐震補強済	0.2		0.1		0.85		0.39	H19	H20			
6	27	大宮小学校	1-24	1-1	1-3	24-0		校舎	S40	R	3	1,365	耐震補強済	0.41		0.57	0.6	0.74		0.82	H22	H23			
	28		2					校舎	S38	R	3	1,297	耐震補強済	0.36		0.29	0.28	0.72		0.55	H20	H22			
	29		3					校舎	S42	R	3	1,268	耐震補強済	0.5		0.5		0.86		0.86	H9	H10			
	30		12-13	12-0	13-0			校舎	S50	R	2	850	耐震補強済	0.4		0.44	0.22	0.82		0.62	H20	H26			
	31		22	1				校舎	S57	R	3	941	新耐震				0.35								
	32		22	2				校舎	S59	R	3	335	新耐震												
	33		5-25	5-0	25-0			体育館	S45	S	2	596	耐震補強済	0.27		0.26		0.87		0.97	H20	H21			
7	34	都跡小学校	1	1	2	7-0	27-0	校舎	S42	R	3	1,330	耐震補強済	0.36		0.39	0.43	0.7		0.75	H21	H22			
	35		2					校舎	S43	R	3	1,484	耐震補強済	0.43		0.47	0.44	0.72		0.78	H21	H23			
	36		26					校舎	S57	R	4	1,756	新耐震				0.39								
	37		33					体育館	H1	R	2	800	新耐震												
8	38	大安寺小学校	16-18	16-1	16-2	18-1a	18-2a	校舎	S53	R	4	4,134	耐震補強済	0.61		0.66	0.77	0.725		0.36	H21	H24			
	39		18	1b	2b			校舎	S54	R	2	859	耐震性有				1.59								
	40		19					体育館	S60	R	2	800	新耐震												
9	41	東市小学校	16	1	3			校舎	S46	R	3	1,071	耐震補強済	0.48		0.52	0.34	0.834		0.51	H22	H24			
	42		16	4				校舎	S47	R	3	380	耐震性有	0.76		0.4	0.46					H22			
	43		24	1	2			校舎	S50	R	3	1,792	耐震補強済	0.381		0.39	0.48	0.73		0.75	H24	H25			
	44		24	4	5	6		校舎	S54	R	3	1,175	耐震補強済	0.577		0.37	0.62	0.71		0.52	H24	H25			
	45		36					体育館	S59	R	2	796	新耐震												
	46		39					校舎	H26	S	3	169	新耐震												
10	47	平城小学校	2	1	2	3		校舎	S35	R	3	1,228	耐震補強済	0.35		0.37	0.39	0.71		0.64	H23	H24			
	48		9					校舎	S35	R	2	72	耐震補強済	0.43		0.58	0.71	0.9		1.06	H23	H24			
	49		11	1				校舎	S46	R	3	696	耐震補強済	0.41	1.03		0.78	2.67			H10	H12			
	50		11	2	3			校舎	S51	R	3	416	耐震補強済	0.55		0.57	0.44	0.72		0.49	H24	H26			
	51		11	4	5			校舎	S52	R	3	641	耐震補強済	0.58		0.46	0.35	0.72		0.42	H24	H26			
	52		11	6	7			校舎	S56	R	3	379	耐震性有				1.79								
	53		19					校舎	S50	R	3	1,432	耐震補強済	0.59		0.37	0.46	0.72		0.35	H23	H24			
	54		29					校舎	S60	R	2	167	新耐震												
11	55	辰市小学校	13	1	3			体育館	S48	S	2	669	耐震補強済	0.35	1.07		0.846	2.508			H17	H21			
	56		13	1	6			校舎	S47	R	3	2,498	耐震補強済	0.3		0.51	0.29	0.75		0.34	H20	H22			
	57		13	2	3	4	5		校舎	S51	R	3	974	耐震補強済	0.45		0.48	0.24	0.84		0.37	H20	H24		
	58		23-1	23-2	24-1	24-2	24-3		校舎	S54	R	3	1,283	耐震補強済	0.368		0.379	0.35	0.74		0.34	H23	H24		
	59		14	1				体育館	S48	S	2	437	耐震補強済	0.12	0.38	0.29	0.72		0.78	H18	H20				
12	60	明治小学校	7	2	3			校舎	S52	R	3	947	耐震補強済	0.53		0.546	0.37	0.81		0.4	H23	H24			
	61		20	1	2			校舎	S54	R	3	1,150	耐震性有				1.36								
	62		22	1	2			校舎	S56	R	3	258	耐震性有	0.721		0.564	0.67					H23			
	63		23					校舎	S57	R	2	414	耐震性有				1.03								
	64		27					校舎	H28	R	3	1,605	新耐震												
	65		31					校舎	H29	R	3	1,136	新耐震												
13	66	帯解小学校	9	1	2a			体育館	S50	S	2	589	耐震補強済												
	67		18	1				校舎	S52	R	2	428	耐震性有	1.16		0.5	0.79					H24			
	68		18	2	3			校舎	S55	R	3	1,011	耐震性有	0.88		0.45	0.59					H24			
	69		20					校舎	S57	R	3	1,320													

耐震化状況一覧表

【小学校】

H31.4.1現在

期別	番号	施設名	棟番号	枝番号.1	枝番号.2	枝番号.3	枝番号.4	建物区分	建築年	構造	階数	延べ面積	耐震性能等	耐震診断(2次診断)結果			1次診断			補強後			2次診断年度	補強設計年度	備考
														IS値	q値	CTuSD値	IS値	IS値	q値	CTuSD値					
26	116	登美ヶ丘小学校	1	1	2	3		校舎	S44	R	3	1,839	耐震補強済	0.26		0.37	0.19	0.74		0.81	H20	H21			
	117		1	4	5			校舎	S52	R	4	945	耐震性有	0.84		0.32	0.64					H21			
	118		2						校舎	S44	R	3	1,444	耐震補強済	0.45	1.1		0.79	1.67			H8	H9		
	119		3	1					校舎	S45	R	3	752	耐震補強済	0.42		0.32	0.33	0.704		0.359	H21	H23		
	120		3	2					校舎	S46	R	3	584	耐震補強済	0.39		0.4	0.3	0.809		0.65	H21	H23		
	121		3	3					校舎	S47	R	3	1,103	耐震補強済	0.49		0.54	0.23	0.723		0.741	H20	H23		
	122		10	1	2	3			校舎	S55	R	3	1,012	耐震補強済	0.61		0.45	0.49	0.73		0.43	H21	H24		
123	4						体育館	S46	R	1	657	耐震補強済	0.14	0.43	0.32		0.87	1.68	0.5		H20	H21			
27	124	六条小学校	1	1	2			校舎	S45	R	3	1,987	耐震補強済	0.45		0.49	0.31					H24	H26		
	125		1	4				校舎	H4	R	4	523	新耐震												
	126		3	1	2				校舎	S46	S	1	217	耐震補強済	0.09	0.36							H24	H26	
	127		4	1	2				校舎	S47	R	3	1,517	耐震補強済	0.35	1.5		0.82	2.8			H12	H13		
	128		4	3					校舎	S49	R	3	261	耐震補強済	0.34		0.36	0.47					H24	H26	
	129		4	4					校舎	S50	R	3	369	耐震補強済	0.48		0.5	0.83					H24	H26	
	130		4	5	6				校舎	S52	R	4	1,252	耐震補強済	0.55		0.51	0.76					H24	H26	
	131		15	1	2				校舎	S55	R	3	664	耐震性有				1.26							
	132		2						体育館	S46	R	2	668	耐震補強済	0.08		0.04		0.85		0.86	H19	H20		
	28		133	青和小学校	1	1	2	3		校舎	S46	R	4	2,737	耐震補強済	0.19		0.26	0.18	0.71		0.65	H20	H21	
134		3	2					校舎	S47	R	3	117	耐震補強済	0.4		0.15	0.43	0.707		0.49	H24	H26			
135		4	1		2				校舎	S47	R	4	1,569	耐震補強済	0.23	1		0.73		0.36	H13	H20			
136		4	3		4				校舎	S53	R	3	607	耐震補強済	0.44	1.53		0.75		0.81	H13	H20			
137		13							校舎	H18	S	2	227	新耐震											
138		14							校舎	H22	S	2	227	新耐震											
139		2							体育館	S46	R	2	703	耐震補強済	0.39		0.17		0.91		0.39	H17	H20		
29	140	右京小学校	1-1	1-2	1-6	1-7	9-0	校舎	S47	R	3	2,225	耐震補強済	0.39		0.414	0.46	0.701		0.74	H24	H25			
	141		1	3				校舎	S51	R	3	383	耐震性有	0.79		0.806	0.36					H24			
	142		1	4	8				校舎	S52	R	3	644	耐震補強済	0.64		0.68	0.35	0.75		0.48	H24	H25		
	143		1	5	9				校舎	S53	R	3	647	耐震補強済	0.43		0.45	0.27	0.79		0.82	H20	H21		
	144		7	1	2	3	4		校舎	S50	R	3	1,461	耐震補強済	0.57		0.619	0.38	0.764		0.83	H24	H25		
	145		2	1	2				体育館	S47	R	2	738	耐震補強済	0.254		0.141		0.76		0.31	H17	H19		
30	146	東登美ヶ丘小学校	3	1	7a			校舎	S48	R	4	3,314	耐震補強済	0.36	1.03			0.73		0.43	H12	H20			
	147		3-2	3-3	3-4	3-6a	3-7b	校舎	S49	R	4	1,469	耐震補強済	0.57		0.58	0.34	0.73		0.77	H23	H24			
	148		3	5	6b				校舎	S54	R	3	660	耐震性有	0.85		0.34	0.38					H23		
	149		4						体育館	S49	R	2	769	耐震補強済	0.06		0.04	0.42	0.84		0.88	H20	H21		
31	150	二名小学校	5	1a				校舎	S48	R	3	1,401	耐震補強済	0.53		0.45	0.58	0.725		0.47	H23	H24			
	151		5	1b				校舎	S48	R	4	1,940	耐震補強済	0.45		0.33	0.48	0.74		0.51	H23	H24			
	152		5	2				校舎	S52	R	3	1,054	耐震補強済	0.44		0.45	0.29	0.85		0.4	H20	H23			
	153		6					体育館	S49	R	2	782	耐震補強済	0.27		0.19		1.16		1.19	H18	H20			
32	154	西大寺北小学校	1	1a				校舎	S50	R	4	3,200	耐震補強済	0.37		0.4	0.31	0.71		0.73	H24	H25			
	155		1	1b				校舎	S50	R	2	265	耐震性有	0.73		0.76	0.57					H24			
	156		9	1	2				校舎	S51	R	3	742	耐震補強済	0.5		0.52	0.54	0.71		0.73	H24	H25		
	157		9	3	4				校舎	S52	R	3	513	耐震補強済	0.57		0.59	0.51	0.71		0.73	H24	H25		
	158		9	5	6				校舎	S54	R	3	998	耐震補強済	0.53		0.55	0.55	0.78		0.8	H24	H25		
159	8	1	2				体育館	S51	R	2	771	耐震補強済	0.22		0.13		0.91		0.94	H18	H19				
33	160	富雄第三小学校	1	1	3			校舎	S51	R	3	1,687	耐震補強済	0.45		0.37	0.28	0.72		0.74	H20	H21			
	161		1-2-3	1-2	2-1b	3-0		校舎	S51	R	3	1,431	耐震補強済	0.17		0.18	0.2	0.72		0.44	H20	H21			
	162		2-13	1a	2	13-0		校舎	S51	R	3	1,698	耐震補強済	0.28		0.33	0.27	0.73		0.77	H20	H21			
	163		11	1	2				校舎	S55	R	3	399	耐震補強済	0.71		0.38	0.36	0.93		0.43	H21	H21		
	164		11	3					校舎	S59	R	2	444	新耐震											
	165		9	1	2				体育館	S51	R	2	800	耐震補強済	0.32		0.15		1.31		1.38	H18	H19		
34	166	平城西小学校	1	1	2			校舎	S54	R	3	2,872	耐震補強済	0.3		0.33	0.42	0.78		0.57	H24	H25			
	167		2	1	2				校舎	S54	R	3	1,404	耐震補強済	0.4		0.43	0.36	0.708		0.67	H24	H25		
	168		5	1	2				体育館	S54	R	2	797	耐震補強済	0.37		0.13		1.93		1.06	H20	H21		
35	169	大安寺西小学校	9	1a	2	3a		校舎	S55	R	3	3,191	耐震補強済	0.66		0.37	0.35	0.71		0.33	H24	H26			
	170		9-17	9-3b	17-0			校舎	S55	R	3	1,943	耐震補強済	0.57		0.45	0.28	0.808		0.47	H20	H24			
	171		10	1	2				体育館	S55	R	2	798	耐震性有	0.88		0.96						H20		
36	172	三碓小学校	1	1	2			校舎	S55	R	3	2,228	耐震補強済	0.65		0.34	0.3	0.78		0.35	H24	H26			
	173		2	1	2a				校舎	S55	R	3	1,370	耐震性有	0.73		0.38	0.63					H24		
	174		2	2b					校舎	S55	R	3	1,386	耐震補強済	0.51		0.35	0.26	0.73		0.42	H20	H24		
	175		11						校舎	H21	S	2	226	新耐震											
	176		4	1	2				体育館	S55	R	2	755	耐震性有	1.93		0.98						H20		
37	177	神功小学校	1	1	2	3		校舎	S55	R	3	1,555	耐震性有	0.75		0.79	0.33					H24			
	178		2	1					校舎	S55	R	3	1,559	耐震性有	0.73		0.81	0.6					H24		
	179		2	2					校舎	H5	R	2	171	新耐震											
	180		2	3					校舎	H8	R	2	171	新耐震											
	181		2	4					校舎	H17	R	2	405	新耐震											
	182		3	1	2				体育館	S55	R	2	597	耐震補											

耐震化状況一覧表

【中学校】

H31.4.1.現在

施設No	番号	施設名	棟番号	枝番号_1	枝番号_2	枝番号_3	枝番号_4	建物区分	建築年	構造	階数	延べ面積	耐震性能等	耐震診断(2次診断)結果			1次診断			補強後			2次診断年度	補強設計年度	備考
														IS値	q値	CTUSD値	IS値	IS値	q値	CTUSD値					
1	1	春日中学校	2	1	2	3		校舎	S41	R	3	1,910	耐震補強済	0.37		0.32	0.31	0.75		0.32	H21	H23			
	2		30					校舎	S51	R	3	2,073	耐震補強済	0.57		0.32	0.6	0.747		0.31	H21	H24			
	3		44					校舎	S55	R	4	1,772	耐震補強済	0.39		0.3	0.37	0.71		0.33	H21	H23			
	4		46					校舎	S57	R	3	1,375	新耐震				0.6								
	5		53	a				校舎	S60	R	2	600	新耐震												
	6		53	b				校舎	S60	R	2	205	新耐震												
	7		60					校舎	H7	S	1	260	新耐震												
	8		52					体育館	S60	R	1	1,100	新耐震												
	9		20					武道場	S47	S	1	240	耐震補強済	0.631	2.52			1.11	2.02			H24	H25		
	10		64					校舎	H25	S	1	252	新耐震												
2	11	三笠中学校	15					校舎	S48	R	4	3,066	耐震補強済	0.45		0.32		0.9		0.38	H8	H8			
	12		16					校舎	S48	R	2	615	耐震性有	1.04		0.59						H10			
	13		17					校舎	S48	R	4	2,070	耐震補強済	0.36	0.36			0.8	1.4	0.35		H9	H11		
	14		18					校舎	S48	R	2	265	耐震性有	0.82		0.53						H10			
	15		19					校舎	S48	R	4	2,626	耐震補強済	0.29		0.3	0.2	0.71		0.75		H20	H21		
	16		36	1	2			校舎	S56	R	3	355	耐震性有	0.8		0.3	0.48					H21			
	17		37					校舎	S57	R	3	655	新耐震												
	18		49					校舎	H28	S	1	76	新耐震												
	19		30					体育館	S50	R	2	1,514	耐震補強済	0.339		0.18		0.93		0.39		H19	H22		
	20		33					武道場	S51	S	1	216	耐震補強済	0.13	0.5			0.72	1.32			H24	H26		
	21		47					校舎	H28	S	1	368	新耐震												
3	22	若草中学校	36	1				校舎	S50	R	3	2,772	耐震補強済	0.49		0.32	0.27	0.73		0.31		H20	H23		
	23		36	3				校舎	H12	R	2	262	新耐震												
	24		48	a				校舎	S54	R	3	2,777	耐震補強済	0.55		0.47	0.4	0.81		0.4		H21	H24		
	25		48	b				校舎	S54	R	2	263	耐震性有	1		0.45	0.69					H21			
	26		48	c				校舎	S54	R	2	192	耐震性有	0.88		0.9	0.4					H21			
	27		57					校舎	S59	R	2	895	新耐震												
	28		55					体育館	S58	R	2	1,100	新耐震												
	29		29-1	29-2	29-3	29-4	29-5	武道場	S48	S	1	323	耐震補強済	0.07	0.26			1.54	2.52			H17	H25		
	30		66					校舎	H28	S	1	253	新耐震												
	31		1	1	2				校舎	S45	R	3	1,406	耐震補強済	0.45		0.37	0.32	0.76		0.3		H21	H23	
4	32	伏見中学校	1	3	4			校舎	S45	R	4	1,656	耐震補強済	0.32		0.35	0.28	0.752		0.82		H20	H22		
	33		2	2				校舎	S41	R	3	635	耐震補強済	0.53	1.8			1.01	2.2			H8	H9		
	34		11	1	2			校舎	S48	R	4	530	耐震補強済	0.35		0.32	0.19	0.76		0.41		H20	H22		
	35		16					校舎	S50	R	3	453	耐震補強済	0.33		0.35	0.43	0.75		0.81		H23	H25		
	36		19	1	2			校舎	S52	R	3	652	耐震性有	0.81		0.48	0.53					H23			
	37		22					校舎	S59	R	4	1,489	新耐震												
	38		18	1	2			体育館	S51	R	2	1,100	耐震補強済	0.29		0.18		0.79		0.64		H19	H20		
	39		14					武道場	S49	S	1	206	耐震補強済	0.65	1.54			0.72	1.44			H24	H26		
	40		29					校舎	H25	S	1	252	新耐震												
	5		41	富雄中学校	1					校舎	S44	R	4	2,081	耐震補強済	0.33		0.35	0.19	0.72		0.52		H20	H22
42		2						校舎	S42	R	3	1,631	耐震補強済	0.45		0.49	0.36	0.78		0.69		H22	H23		
43		3						校舎	S39	R	3	1,057	耐震補強済	0.49		0.53	0.43	0.883		0.46		H22	H24		
44		16	1		2			校舎	S53	R	3	1,150	耐震補強済	0.638		0.59	0.7	0.73		0.7		H24	H25		
45		22	1		2			校舎	S55	R	4	246	耐震補強済	0.41		0.24	0.5	0.71		0.35		H24	H25		
46		27						校舎	S59	R	2	494	新耐震												
47		33						校舎	H2	R	2	532	新耐震												
48		25						体育館	S58	R	2	1,016	新耐震												
49		11						武道場	S47	S	1	223	耐震補強済	0.38	1.52			0.72	2.41			H24	H26		
50		40						校舎	H25	S	1	309	新耐震												
6	51	都南中学校	2	3	4			校舎	S52	R	3	831	耐震補強済	0.36	1.13	0.34		0.765		0.82		H13	H24		
	52		15	1				校舎	S48	R	3	961	耐震補強済	0.5	1.8			0.78		0.54		H13	H17		
	53		15	2	3			校舎	S55	R	3	630	耐震補強済	0.539		0.34	0.33	0.75		0.34		H24	H25		
	54		35	a				校舎	S58	R	4	2,201	新耐震												
	55		35	b				校舎	S58	R	4	2,072	新耐震												
	56		43					校舎	H4	R	4	579	新耐震												
	57		45					体育館	H15	R	2	1,368	新耐震												
	58		14					武道場	S47	S	1	245	耐震補強済	0.32	0.96			0.99	1.44			H24	H26		
	59		51					校舎	H28	S	1	326	新耐震												
7	60	田原中学校	18					校舎	S56	R	3	1,250	耐震性有	0.789		0.43	0.69					H24			
	61		20					校舎	S57	R	3	398	新耐震				0.61								
	62		21					体育館	S59	R	2	701	新耐震												
	63		17					武道場	S50	S	1	216	耐震補強済	0.26	0.82			0.93	1.7			H24	H26		
9	64	興東館柳生中学校	13					校舎	S62	R	3	1,500	新耐震												
	65		18					体育館	H5	R	2	631	新耐震												
	66		21					武道場	H25	S	1	168	新耐震												
	67		1	1	2a			校舎	S46	R	4	3,028	耐震補強済	0.37		0.38	0.25	0.74		0.75		H20	H22		
10	68	登美ヶ丘中学校	4	1				校舎	S46	R	4	1,725	耐震補強済	0.43		0.32		0.72		0.4		H12	H13		
	69		4	2				校舎	S49	R	3	646	耐震補強済	0.69		0.71	0.4	0.74		0.71		H23	H25		
	70		4	3				校舎	S54	R	3	780	耐震性有	0.852		0.32	0.53					H24			
	71		4	4				校舎	S54	R	3	779	耐震補強済	0.611		0.46	0.51	0.79		0.36		H24	H25		
	72		23					体育館	H9	R	2	1,103	新耐震					</							

